

# Table of Contents

<b>1.0</b>	<b>Introduction</b>	<b>1-1</b>
1.1	Compatibility with Earlier Versions	1-1
1.2	Additional Information	1-2
1.3	Related Hardware and Software	1-2
<b>2.0</b>	<b>Programming For AutoMax Systems</b>	<b>2-1</b>
2.1	Configuration	2-1
2.2	AutoMax Application Tasks	2-2
2.3	UDC Application Tasks	2-3
2.4	AutoMax Programming Conventions	2-3
2.4.1	Naming	2-3
2.4.2	Constants	2-4
2.4.3	Variables	2-5
2.4.4	Arrays	2-6
2.4.5	Variable Control Types	2-8
2.4.6	Pre-defined Common Memory Variables	2-9
<b>3.0</b>	<b>Control Block Programming</b>	<b>3-1</b>
3.1	Format of Control Blocks	3-1
3.2	Task Execution	3-1
3.3	Variable Definition and Initialization	3-2
<b>4.0</b>	<b>Scan Loop</b>	<b>4-1</b>
<b>5.0</b>	<b>Absolute Value</b>	<b>5-1</b>
<b>6.0</b>	<b>Alarm</b>	<b>6-1</b>
<b>7.0</b>	<b>Amplifier</b>	<b>7-1</b>
<b>8.0</b>	<b>And</b>	<b>8-1</b>
<b>9.0</b>	<b>Bit Select</b>	<b>9-1</b>
<b>10.0</b>	<b>Compare</b>	<b>10-1</b>
<b>11.0</b>	<b>Counter</b>	<b>11-1</b>
<b>12.0</b>	<b>Difference</b>	<b>12-1</b>
<b>13.0</b>	<b>Function Generator</b>	<b>13-1</b>
<b>14.0</b>	<b>Inverter</b>	<b>14-1</b>
<b>15.0</b>	<b>Latch</b>	<b>15-1</b>
<b>16.0</b>	<b>Limit</b>	<b>16-1</b>
<b>17.0</b>	<b>Move</b>	<b>17-1</b>
<b>18.0</b>	<b>Multiply And Divide</b>	<b>18-1</b>

<b>19.0 Or</b> .....	<b>19-1</b>
<b>20.0 Pack Bits</b> .....	<b>20-1</b>
<b>21.0 Pulse Multiplier</b> .....	<b>21-1</b>
<b>22.0 Ramp</b> .....	<b>22-1</b>
<b>23.0 Read Bits</b> .....	<b>23-1</b>
<b>24.0 Read Words</b> .....	<b>24-1</b>
<b>25.0 Running Average</b> .....	<b>25-1</b>
<b>26.0 S Curve</b> .....	<b>26-1</b>
<b>27.0 Sampled Average</b> .....	<b>27-1</b>
<b>28.0 Scale</b> .....	<b>28-1</b>
28.1 Overflow Handling .....	28-2
28.2 Application Notes .....	28-2
<b>29.0 Search</b> .....	<b>29-1</b>
<b>30.0 Shift Bits</b> .....	<b>30-1</b>
<b>31.0 Shift Words</b> .....	<b>31-1</b>
<b>32.0 Select</b> .....	<b>32-1</b>
<b>33.0 Summer</b> .....	<b>33-1</b>
<b>34.0 Switch</b> .....	<b>34-1</b>
<b>35.0 Tach Loss and Overspeed</b> .....	<b>35-1</b>
35.1 Setup Calculations and Block Equations .....	35-3
<b>36.0 Thermal Overload</b> .....	<b>36-1</b>
36.1 Setup Calculations and Block Equations .....	36-3
36.2 Special Notes .....	36-3
<b>37.0 Transition</b> .....	<b>37-1</b>
<b>38.0 Unpack Bits</b> .....	<b>38-1</b>
<b>39.0 Write Bits</b> .....	<b>39-1</b>
<b>40.0 Write Words</b> .....	<b>40-1</b>
<b>CONTROL BLOCKS Dependent Upon the SCAN LOOP BLOCK</b> .....	<b>41-1</b>
<b>41.0 Differentiator Lag</b> .....	<b>41-2</b>
41.1 DIFF_LAG wm Limitations .....	41-3
41.2 DIFF_LAG wlg Limitations .....	41-4

<b>42.0 Integrate</b>	<b>42-1</b>
42.1 INTEGRATE wm Limitations	42-2
42.2 INTEGRATE K1 Limitations	42-3
42.3 Calculating K1 for INTEGRATE Time Domain Applications	42-3
<b>43.0 LAG</b>	<b>43-1</b>
43.1 LAG wm Limitations	43-2
43.2 LAG wlg Limitations	43-3
<b>44.0 LEAD/LAG</b>	<b>44-1</b>
44.1 LEAD_LAG, wld, wlg, and wm Limitations	44-2
<b>45.0 Notch Filter</b>	<b>45-1</b>
<b>46.0 High-pass Filter (Nth Order High-Pass Butterworth Filter)</b>	<b>46-1</b>
46.1 HIGH_PASS_FILTER wld Limitations	46-2
<b>47.0 Low_Pass_Filter (Nth Order Low-Pass Butterworth Filter)</b>	<b>47-1</b>
47.1 LOW_PASS_FILTER wlg Limitations	47-2
<b>48.0 Notchn (Nth Order Notch Filter)</b>	<b>48-1</b>
48.1 NOTCHN wn Limitations	48-2
<b>49.0 Proportional + Integral</b>	<b>49-1</b>
49.1 PROP_INT wm Limitations	49-3
49.2 PROP_INT wld Limitations	49-3
49.3 PROP_INT KP Limitations	49-4
<b>50.0 PID</b>	<b>50-1</b>
50.1 KP Limitations	50-7
50.2 KI Limitations	50-7
50.3 KD Limitations	50-8
50.4 LOOP_TIME Limitations	50-8
50.5 DEAD_BAND Limitations	50-8
50.6 MAX_CHANGE Limitations	50-8
<b>51.0 Special Coefficient Restrictions</b>	<b>51-1</b>
<b>52.0 D-C Drive Current Minor Loop</b>	<b>52-1</b>
52.1 Input Keyword Definitions	52-3
52.1.1 Physical Configuration Inputs	52-5
52.1.2 Loop Control Inputs	52-5
52.1.3 Sequencing Control Inputs	52-7
52.1.4 Test Mode Inputs	52-8
52.1.5 Drive Faults Programming Inputs	52-8
52.1.6 Drive Controller Module (57C406) Switch Outputs	52-11
52.2 Output Keyword Definitions	52-11
52.2.1 Loop Control Outputs	52-11
52.2.2 Drive Faults and Diagnostic Outputs	52-12
52.3 Power Module Diagnostic Enhancements	52-13
52.3.1 Shorted SCR Diagnostic	52-14
52.3.2 Diagnostic Data Collection	52-15

52.4 Tach Loss Delta Threshold Adjustment .....	52-17
52.4.1 Making Tach Loss Adjustments .....	52-17
52.5 Line Synchronization Filter Adjustments .....	52-19
52.5.1 PLL Filter Adjustments .....	52-19
52.6 Fast Bridge Change .....	52-20
52.6.1 Hardware Requirements .....	52-22
52.6.2 Software Requirements .....	52-22
52.7 Drive I/O Controller Write Registers .....	52-22
<b>53.0 Execution Time Estimates .....</b>	<b>53-1</b>
53.1 AutoMax Processor and AutoMax PC3000 Control Block Tasks .....	53-1
53.2 UDC Tasks .....	53-1

# Appendices

<b>Appendix A</b>	
Converting a Control Block Task to the Most Current Version . . . . .	A-1
<b>Appendix B</b>	
BASIC Language Statements and Functions in AutoMax Control Block Tasks . . . . .	B-1
<b>Appendix C</b>	
Control Blocks Supported in UDC Control Block Tasks . . . . .	C-1
<b>Appendix D</b>	
BASIC Language Statements and Functions in UDC Control Block Tasks . . . . .	D-1

# List of Figures

Figure 28.1 - Converting 4-20ma to 0-10000 counts .....	28-3
Figure 50.1 - PID Block Diagram .....	50-3

# List of Tables

Table 1 - Input Parameters Summary .....	52-4
Table 2 - Organization of DIAG_DATA Array .....	52-16
Table 3 - Maximum Armature Inductance for Fast Bridge Change .....	52-21
Table 4 - Maximum Execution Time Summary - AutoMax Tasks .....	53-2
Table 5 - Maximum Execution Time Summary - UDC Tasks .....	53-3
Table 6 - Maximum Execution Time Summary - AutoMax PC3000 Tasks .....	53-4